
Endogenous Mucopolysaccharidosis Type I (IDUA [Alpha-L-Iduronidase]) Biomarker Reflex, Blood Spot

Test ID: MPS1R

Explanation:

Due to a reagent issue, [MPS1R: MPS1 Biomarker Reflex, BS](#) will be Test Down, effective immediately. Clients who have samples currently pending will be contacted by the Genetic Counselor Team to discuss testing options.

Clients with samples pending for newborn screening will have the option to switch testing to [MPS1B: Endogenous Mucopolysaccharidosis Type I \(IDUA \[Alpha-L-Iduronidase\]\) Biomarker, Blood Spot](#) or [MPS2B: Endogenous Mucopolysaccharidosis Type II \(I2S \[Iduronate-2-Sulfatase\]\) Biomarker, Blood Spot](#), as indicated by their Tier 1 Newborn Screening Results. Clients wishing to send testing for newborn screening can also consider ordering [MPS1B](#) or [MPS2B](#) in the interim.

Clients with samples pending for monitoring and/or follow-up testing do not have an alternative due to sample type. However, clients who wish to send monitoring and/or follow-up testing in the interim can consider ordering [MPSQU: Mucopolysaccharides Quantitative, Random, Urine](#) or [MPSER: Mucopolysaccharides Quantitative, Serum](#) for future orders.

Questions

Contact Melissa Tricker-Klar, Laboratory Resource Coordinator at 800-533-1710.