

Buprenorphine Screen, Random, Urine

Test ID: BUPS

Explanation: Testing is currently delayed due to vendor reagent issues. Testing will remain orderable and specimens will be stabilized until testing is able to resume. An update will be provided when additional reagent is received.

Questions

Contact Brandon DeBoom, Laboratory Technologist Resource Coordinator at 800-533-1710.