

Buprenorphine Screen with Reflex, Random, Urine

Test ID: BUPR

Explanation: We are currently unable to perform Buprenorphine Screen (Test component BUPR) testing at this time due to vendor reagent issues. Testing will remain orderable and confirmation testing (Reflex test BUPM) will be added and performed on all incoming orders until additional screening reagent is received. An update will be provided when normal testing patterns resume.

Questions

Contact Brandon DeBoom, Laboratory Technologist Resource Coordinator at 800-533-1710.