

CPT CODE UPDATES**NOTIFICATION DATE:** January 21, 2011**EFFECTIVE DATE:** January 26, 2011**VON WILLEBRAND FACTOR ACTIVITY, PLASMA
89792**

EXPLANATION: The previous new test announcement on December 23, 2011 listed the incorrect CPT code for this test.

Unit Code 83099 – von Willebrand Factor Activity, P Updated CPT code: 85397

This Test is a member of the following new orderable profiles, which become effective on January 26, 2011:

Test Code	Published Name
83094	Bleeding Diathesis Profile, Limited
83099	von Willebrand Profile

QUESTIONS: Contact your Mayo Medical Laboratories' Regional Manager
Kim J. Baker, Mayo Medical Laboratories' Technologist Support
Telephone: 800-533-1710