

Buprenorphine Screen, Random, Urine

Test ID: BUPS

Explanation: The reagent issues affecting this test have been resolved. Testing will resume immediately.

Questions

Contact Brandon DeBoom, Laboratory Technologist Resource Coordinator at 800-533-1710.